

TOP SECRET

Approved For Release 2002/06/10 : CIA-RDP69B00041R001300020003-0

25X1A



2750-67

Copy 6 of 11

18 December 1967

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6738

1. Mission critique was conducted in the OSA Control Center at 1400 hours, 13 December 1967.

2. Mission Data:

- a. Mission Number: BX6738
- b. Date Flown: 10 December 1967
- c. Area of Operation: Cambodia
- d. Mission Success: Successful
- e. Pilot's Name:
- f. Aircraft Number: 131
- g. Primary or Spare Flown: Primary
- h. Takeoff Time - Planned: 0200Z
Actual: 0159Z
- i. Landing Time - Planned: 0611Z
Actual: 0550Z
- j. Time Enroute - Planned: 4+11
Actual: 3+51
- k. Departure Base: Kadena AB
- l. Landing Base: Kadena AB
- m. Equipment:

25X1A

25X1D

25X1D

(1) Primary: Type I,

(2) Spare: Same as primary.

25X1A

HANDLE VIA
COMINT CONTROL
CHANNELS JOINTLY

GROUP 1
Excluded from automatic
downgrading and
declassification

OX CART / TRINE

Approved For Release 2002/06/10 : CIA-RDP69B00041R001300020003-0

3. Operations:

a. Route (INS Plot vs. Planned): Satisfactory.

(1) Comments: Aircraft slightly overahot planned track during turns.

25X1D 25X1D

(2) INS Terminal Error: ☐ NM(3) INS Spec Error: ☐ NM

b. Mission Generation & Operational Support: Satisfactory.

4. Weather:

a. Forecast vs. Actual:

(1) As briefed.

25X1A

(2) Comments: Forecast Cat II; few patches Cat III thin cirrus. Pilot reported generally Cat I. ☐ reported 95 percent cloud-free on first pass and 75 percent on second pass for primary and secondary target areas.

b. Weather Scout Reporting: Satisfactory.

5. Intelligence:a. Target Coverage:

High quality, virtually cloud-free coverage was obtained on the seven priority search areas in Northeast Cambodia. No significant activity was noted.

In other areas, valuable photography was accomplished on certain roads and trails in Southern Laos, Northeast Cambodia and the tri-border area.

b. Quality of Take: Satisfactory.

25X1A

HANDLE VIA ☐
COMINT CONTROL
CHANNELS JOINTLY

(2) Camera Operation: No major discrepancies or problems reported.

- c. Hostile Reaction: None.
d. Significant Findings: None.
e. [REDACTED]
f. Take Movement:
[REDACTED] Photography: Satisfactory.
[REDACTED]

6. Materiel:

- a. Aircraft General: Satisfactory.
b. Aircraft Systems: Satisfactory.

7. Communications:

- a. Message Traffic: Satisfactory.
b. [REDACTED]
c. UHF/HF Commo: Satisfactory.

8. Significant Actions Taken:

Flight plans revised to provide 1.2 MACH at FL290 to [REDACTED]
[REDACTED] refueling area.

9. Outstanding Actions Required:

- a. Investigate INS/autopilot overshoot on turns (Materiel Division).

Deputy for Operations, OSA

TOP SECRET

Approved For Release 2002/06/10 : CIA-RDP69B00041R001300020003-0

25X1A

2750-67
Page 4

OXC/O/OSA/

Distribution:

- #1 - D/SA
- #2 - D/O/OSA
- #3 - D/M/OSA
- #4 - D/R&D/OSA
- #5 - OXC/O/OSA
- #6 - Intel/O/OSA
- #7 - Wea/O/OSA
- #8 - Commo/O/OSA
- #9 - ADP/O/OSA
- #10 - RB/OSA
- #11 - Chrono

25X1A

HANDLE VIA
COMINT CONTROL
CHANNELS JOINTLY

OXCARTRINE

Approved For Release 2002/06/10 : CIA-RDP69B00041R001300020003-0